## 10 1000 Jobsite Inspections

## **JOBSITE INSPECTIONS**

At a minimum	, the jobsite superi	ntendent shall chec	k the work	area each d	ay at the l	beginning o	f each shif
and again at th	e end of each work	k shift to ensure safe	e working o	conditions.			